See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−1N, 1

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−2N, 11

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−1N, 5

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−2N, 51

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−3N, 2

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−4N, 21

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−3N, 6

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−4N, 61

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−5N, 3

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−6N, 31

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−5N, 7

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−6N, 71

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−7N, 4

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−8N, 41

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−7N, 8

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−8N, 81

See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−1N, 1

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−2N, 12

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−1N, 5

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−2N, 52

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−3N, 2

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−4N, 22

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−3N, 6

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−4N, 62

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−5N, 3

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−6N, 32

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−5N, 7

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−6N, 72

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−7N, 4

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−8N, 42

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−7N, 8

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−8N, 82

See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−1N, 1

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−2N, 13

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−3N, 2

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−4N, 23

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−5N, 3

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−6N, 33

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−7N, 4

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−8N, 43

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−1N, 5

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−2N, 53

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−3N, 6

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−4N, 63

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−5N, 7

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−6N, 73

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−7N, 8

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−8N, 83

See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with *a* = 1,00; *b* = 1,00



LE700−1N, 1



LE700−2N, 14

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,75



LE700−3N, 2



LE700−4N, 24

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with *a* = 1,00; *b* = 0,50



LE700−5N, 3



LE700−6N, 34

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with *a* = 1,00; *b* = 2,00



LE700−7N, 4



LE700−8N, 44

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with *a* = 0,75; *b* = 1,00



LE701−1N, 5



LE701−2N, 54

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with *a* = 0,50; *b* = 1,00



LE701−3N, 6



LE701−4N, 64

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with *a* = 0,25; *b* = 1,00



LE701−5N, 7



LE701−6N, 74

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with *a* = 0,00; *b* = 1,00



LE701−7N, 8



LE701−8N, 84

See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with a = 1,00; b = 1,00



LE700−1N, 1

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with a = 1,00; b = 1,00



LE700−2N, 15

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with a = 1,00; b = 0,75



LE700−3N, 2

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with a = 1,00; b = 0,75



LE700−4N, 25

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with a = 1,00; b = 0,50



LE700−5N, 3

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with a = 1,00; b = 0,50



LE700−6N, 35

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with a = 1,00; b = 2,00



LE700−7N, 4

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with a = 1,00; b = 2,00



LE700−8N, 45

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with a = 0,75; b = 1,00



LE701−1N, 5

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with a = 0,75; b = 1,00



LE701−2N, 55

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with a = 0,50; b = 1,00



LE701−3N, 6

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with a = 0,50; b = 1,00



LE701−4N, 65

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with a = 0,25; b = 1,00



LE701−5N, 7

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with a = 0,25; b = 1,00



LE701−6N, 75

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with a = 0,00; b = 1,00



LE701−7N, 8

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with a = 0,00; b = 1,00



LE701−8N, 85

See original or copy: http://web.me.com/klaus.richter/LE70/LE70L0NA.TXT /.PS
Technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20110301-LE70/LE70L0NA.TXT /.PS
application for measurement of printer or monitor systems
TUB material: code=rha4ta

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with a = 1,00; b = 1,00



LE700−1N, 1

Colorimetric transformation *i* = 0
$c_i^* = c_0^* = a\,c^{*b}$ with a = 1,00; b = 1,00



LE700−2N, 16

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with a = 1,00; b = 0,75



LE700−3N, 2

Colorimetric transformation *i* = 1
$c_i^* = c_1^* = a\,c^{*b}$ with a = 1,00; b = 0,75



LE700−4N, 26

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with a = 1,00; b = 0,50



LE700−5N, 3

Colorimetric transformation *i* = 2
$c_i^* = c_2^* = a\,c^{*b}$ with a = 1,00; b = 0,50



LE700−6N, 36

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with a = 1,00; b = 2,00



LE700−7N, 4

Colorimetric transformation *i* = 3
$c_i^* = c_3^* = a\,c^{*b}$ with a = 1,00; b = 2,00



LE700−8N, 46

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with a = 0,75; b = 1,00



LE701−1N, 5

Colorimetric transformation *i* = 4
$c_i^* = c_4^* = a\,c^{*b}$ with a = 0,75; b = 1,00



LE701−2N, 56

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with a = 0,50; b = 1,00



LE701−3N, 6

Colorimetric transformation *i* = 5
$c_i^* = c_5^* = a\,c^{*b}$ with a = 0,50; b = 1,00



LE701−4N, 66

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with a = 0,25; b = 1,00



LE701−5N, 7

Colorimetric transformation *i* = 6
$c_i^* = c_6^* = a\,c^{*b}$ with a = 0,25; b = 1,00



LE701−6N, 76

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with a = 0,00; b = 1,00



LE701−7N, 8

Colorimetric transformation *i* = 7
$c_i^* = c_7^* = a\,c^{*b}$ with a = 0,00; b = 1,00



LE701−8N, 86